

25V-406

Dear Foretravel Owner:

Foretravel Motorcoach has decided that a defect, which relates to motor vehicle safety, exists in certain 2024, 2025 and Early 2026 MY, Foretravel FS605 and FS605P vehicles.

This notice applies to the vehicle identification number below;

The Driver and Passenger Rear Kick Up Panels Vertical grill fins may show fatigue at the upper or lower attachments due to engine vibration

What is the defect?

Corrective Action

Install Center Stiffener horizontally across the grill area to add stability to the individual vertical fins. The repair will take approximately 1.0 hr. to complete.
Contact Service Dealer to schedule for an inspection of the D6 and P6 fins to determine if repairs are needed.

IMPORTANT SAFETY RECALL NOTICE

This will be done at no charge parts and labor to you or the consumer. We will notify owners of the affected vehicles and direct them to Foretravel Authorized dealer to have the remedy applied. For assistance, you may call Foretravel Customer Assistance and Technical Support at 1-800-955-6226

Foretravel Motorcoach and its brands are committed to customer safety and satisfaction.

Please note: The service will be provided at no cost to you, the vehicle owner.

What Should You Do

You may call Foretravel Inc. at 1-800-955-6226 opt 3 to help attain a scheduled service repair with Foretravel of Texas for needed Recall repairs. Steps will be taken to ensure the recall is performed as necessary for your Safety.

Reimbursement

The driver and passenger kick up panel doors will have the Center Stiffener Installed horizontally across the grill area to add stability to the individual vertical fins.

This will be done at no charge to you or the consumer.

For more information contact Foretravel Inc. at 1-800-955-6226 opt 3.

If the authorized service center has failed or is unable to remedy the defect without charge and within a reasonable time, contact Foretravel Inc. at 1-800-955-6226 opt. 3. If you are still not able to have the safety defect remedied without charge and within a reasonable time, you may submit a written complaint to:

Administrator,
National Highway Traffic Safety Administration,
1200 New Jersey Avenue SE,
Washington, D.C. 20590

You may also call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to www.NHTSA.gov if you feel the manufacture has failed or is unable to remedy the defect without charge.

IMPORTANT SAFETY RECALL NOTICE

Reply Card


The enclosed owner reply card identifies your vehicle. Presentation of this card to the service center will assist in making the necessary correction in the shortest possible time. If you have sold or traded the vehicle, please let us know by completing the postage paid reply card and returning it to us.

Lessor

Federal Law requires that you forward a copy of this safety recall notice to the lessee within 10 days.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products.

Sincerely,



James Triana
Foretravel Inc.
Director of Warranty and Customer Service