

IMPORTANT SAFETY RECALL

26V-464

July 20, 2026

Dear Foretravel Owner:

This notice is sent to you in accordance with the **National Traffic and Motor Vehicle Safety act**.

Foretravel Motorcoach has decided that a defect, which relates to motor vehicle safety exist in certain 2027 MY, Foretravel Realm FS605P vehicles.

Please Note: Foretravel Motorcoach has 3 vehicles involved with this recall. This notice applies to the vehicle identification number below;

4VZ1U1R13VC096219

NHTSA Recall No. 26V-464

Foretravel Motorcoach has decided that a defect in certain 2027 MY, Foretravel Realm FS605P vehicles exist.

The Airxcel Vent Fan affected were fabricated and delivered to Foretravel from January 5, 2026 through June 17, 2026. The affected PCBs were built between December 15, 2025 and June 17, 2026.


Please note: The Vehicle Identification Number that may be affected by this recall is located at the top of this letter.

What is the defect?

The defect which relates to motor vehicle safety exists in its MaxxFan Fan. The printed circuit board (PCB) installed in the fan assembly contains a safety defect that can result in overheating of the PCB that could result in a fire.

The affected part numbers are:

- ☒ 00-04700NX - MaxxFan Plus
- ☐ 00-04900NX – MaxxFan Plus
- ☐ 00-04950NX – MaxxFan Plus
- ☐ 00-08950N – MaxxFan DLX
- ☐ 00-08900N – MaxxFan DLX
- ☐ 10B21275N – Network PC Board



IMPORTANT SAFETY RECALL

26V-464

Corrective Action

The recall remedy is to inspect the MaxxAir fan and replace the PCB if found within the range of suspect products. The inspection should take approximately 15 minutes and an additional 15 minutes if the PCB needs to be replaced. Foretravel will provide this remedy at no cost to owners. With proper documentation, Foretravel will reimburse owners per its general reimbursement policy if their MaxxAir fan was remedied prior to the issuing of this recall.

Please contact your Foretravel dealer as soon as possible to arrange an inspection date for your vehicle. Inspection photos of the Printed Circuit Board Serial Number can also be sent to Foretravel to determine if the recall repair will be required. The PCB inspection photos can be sent to Noreply@foretravel.com

This will be done at no charge parts and labor to you or the consumer. We will notify owners of the affected vehicles and direct them to Foretravel Authorized dealer to have the remedy applied. For assistance, you may call Foretravel Customer Assistance and Technical Support at 1-800- 955-6226

Foretravel Motorcoach and its brands are committed to customer safety and satisfaction.

Please note: The service will be provided at no cost to you, the vehicle owner.

What Should You Do

You may call Foretravel Inc. at 1-800-955-6226 opt 3 to help attain a scheduled service repair with Foretravel of Texas for needed Recall repairs. Steps will be taken to ensure the recall is performed as necessary for your Safety.

Reimbursement

Owners who have made repairs prior to recall notification of the recall may be eligible for reimbursement by contacting Foretravel Warranty and Customer assistance.

This will be done at no charge to you or the consumer.

For more information contact Foretravel Inc. at 1-800-955-6226 opt 3.

If the authorized service center has failed or is unable to remedy the defect without charge and within a reasonable time, contact Foretravel Inc. at 1-800-955-6226 opt. 3. If you are still not able to have the safety defect remedied without charge and within a reasonable time, you may submit a written complaint to:

IMPORTANT SAFETY RECALL

26V-464

Administrator,
National Highway Traffic Safety Administration,
1200 New Jersey Avenue SE, Washington, D.C.
20590

You may also call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-888-275-9171); or go to www.NHTSA.gov if you feel the manufacture has failed or is unable to remedy the defect without charge.

Reply Card


The enclosed owner reply card identifies your vehicle. Presentation of this card to the service center will assist in making the necessary correction in the shortest possible time. If you have sold or traded the vehicle, please let us know by completing the postage paid reply card and returning it to us.

Lessor

Federal Law requires that you forward a copy of this safety recall notice to the lessee within 10 days.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products.

Sincerely,

A handwritten signature in blue ink, appearing to read "J. Triana", is positioned above the printed name and title.

James Triana
Foretravel Inc.
Director of Warranty and Customer Service

IMPORTANT SAFETY RECALL

26V-464

